

INDIAN BUREAU OF MINES

--:-- Inspection Report --:--

Part-I : General Information

1.1.1 Mine Details

Name of the Mine :	07GUJ07111	Lease Area (Ha) :	53.61
Forest Area (Ha) :	N/A	Mine Code :	07GUJ07111
Registration Number :	IBM/6251/2011	Name of lessee :	Ramnklal
Address of lessee :	Jeevan Jyot ,M.G.Road, Porbandar	Phone of lessee :	0286-2244042
Email of lessee :	Accounts@thankys.com	Fax Number :	N/A
Village :	Jamnagar City	Taluka / Mandal :	Jamnagar City
District :	Jamnagar	Pincode :	360575
State :	Gujarat	Post Office :	N/A
Nearest Police Station :	N/A	Nearest Railway Station :	N/A
Date of Grant of Mining Lease :	1996-02-05	Date of Mining Lease Execution :	1996-02-05
Date of opening in the mine :	Nilsss		

Nominated Owner Details			
Name of the Nominated Owner :	N/A	Nominated Owner Address:	N/A
Nominated Owner Mobile :	N/A	Nominated Owner Email :	N/A
Nominated Owner Fax Number :	Nil	Date of Nominated Owner Appointment :	Nil
Mining Engineer Details			
Name of the Mining Engineer :	Nil	Qualification of Mining Engineer :	Nil
Address of Mining Engineer :	Nil	Phone of Mining Engineer :	N/A
Email of Mining Engineer :	N/A	Fax Number of Mining Engineer :	N/A
Date of Mining Engineer Appointment :	Nil		
Geologist Details			
Name of the Geologist :	K S Nagori	Qualification of Geologist :	MSc Geology
Address of Geologist :	Rajasthan	Phone of Geologist :	N/A
Email of Geologist :	N/A	Fax Number of Geologist :	N/A
Date of Geologist Appointment :	Nil		
Mine Manager Details			
Name of the Mine Manager :	Harish G Thanki	Qualification of Mine Manager :	BE
Address of Mine Manger :	Porbandar	Phone of Mine Manger :	N/A
Email of Mine Manger :	N/A	Fax Number of Mine Manger :	N/A
Date of Mine Manger Appointment :	Nil		

Mineral(s) granted in lease and proved for mining :	BAUXITE	Date of Approval of Mining Plan / Modified Mining Plan / ROMP with five-year period :	2025-12-02 (2026 - 2030)
Method of mining :	Open Cast	Category :	N/A
Nature of Use :	Non Captive		

Part-II : Other Information

2.1.1 : Inspection Details

Inspecting Officer :	Debajyoti Nayak
Designation :	Inspection Officer
Name of the Accompanying Official from Mine :	K.C. Nagori and Harish G Thanki
Designation of the Accompanying Official :	QP & Mines Agent
Type of Inspection :	MCDR,MPAS,STR
Date of Inspection :	23/09/2025
Review year considered for MCDR Inspection :	2024-2025

Final Submitted

2.2.1 : Exploration Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Number of Core Boreholes	Not Proposed.	50	50	No Violation
Remark: A total of 50 core boreholes were proposed in 2023–24. However, the lessee did not carry out the drilling. Following violation compliance, all 50 core boreholes were subsequently completed in 2024–25. Remark File: NIL					
2	Number of DTH Boreholes	Not Proposed.	NA	NA	No Violation
Remark: NIL Remark File: NIL					
3	Number of exploratory pits / trial pits	Not Proposed.	NA	NA	No Violation
Remark: NIL Remark File: NIL					
4	Number of exploratory Trenches	Not Proposed.	NA	NA	No Violation
Remark: NIL Remark File: NIL					
5	Lateral exploration status for the lease area - G1	53.61	53.61	0.000	No Violation
Remark: A total of 50 borehole drillings were carried out in 2024-25. The total leased area has been explored at the G1 level of exploration, so no proposal was given.					

Remark File: NIL					
6	Lateral exploration status for the lease area-G2	Nil	Nil	Nil	No Violation
Remark: NIL Remark File: NIL					
7	Lateral exploration status for the lease area-G3	0.00	Nil	Nil	No Violation
Remark: NIL Remark File: NIL					
8	Lateral exploration status for the lease area-G4	Nil	Nil	Nil	No Violation
Remark: NIL Remark File: NIL					
9	UNFC category wise reported Resources/Reserves as per MP/MMP ROMP Total Reserves (111, 121 & 122) and Total Mineral Resources (331, 332 & 333 upto 334)	BAUXITE - Total Reserve: 2,928,540.00, Total Resource 273,680.00	Total Reserves (T): 111-547920.00, 122-2380620.00, Total Mineral Resources: 221-74580.00, 222-199100.00	Nil	No Violation
Remark: No production was reported in 2024-25. Mining operations have not started because Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance notice of mine) Remark File: NIL					

Final Submitted

2.3.1 : Development - Opencast Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Location of development w.r.t. lease area	Pit : Pit 8 & Direction : North	Development work not carried out.	Pit : Pit 8 & Direction: North	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance notice of mine) Remark File: NIL					
2	Quantity of overburden generation in m3	28762.00	0	28762.000	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals are yet to be obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance notice of mine) Remark File: NIL					
3	Quantity of topsoil generation in m3	14381.00	0	14381.000	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of Mine). Remark File: NIL					
4	Stripping ratio : ore to OB ratio	8.69200000	0	8.692	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals are yet to be obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					

2.4.1 Exploitation - Opencast Mine Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Number of pits / Blocks proposed for production	Pit ID : Pit 8	Production not carried out.	Pit ID : Pit 8	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
2	Quantity of ROM mineral production proposed (in T)	249999.20	0	249999.200	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
3	Recovery of salable/usable mineral quantity from ROM production in T)	237499.24	0	237499.240	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
4	Quantity of mineral reject/Sub-grade generation	12499.96	0	12499.960	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
5	Grade of mineral reject/sub-grade generation as per	Not Proposed.	NA	NA	No Violation

	threshold value declared				
Remark: NIL Remark File: NIL					
6	Manual/Mechanised method adopted for segregating subgrade/mineral rejects from ROM	Manual	No work carried out.	NA	No Violation
Remark: NIL Remark File: NIL					
7	Whether height of benches in Overburden& mineral suitable for method of mining proposed in mining plan	height of benches in Overburden& mineral suitable for method of mining proposed in mining plan	Yes, the height of the mineral bench was max. 6 metes	Nil	No Violation
Remark: NIL Remark File: NIL					
8	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					

2.4.3 : Exploitation - Dump Working Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Number of dumps	Not Proposed	NA	NA	No

	proposed for production				Violation
Remark: NIL Remark File: NIL					
2	Quantity of dump material handling Proposed (in Tonne)	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					
3	Recovery of salable/usable mineral from dump production (in Tonne)	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					
4	Production from dump(s) during the year	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					
5	Quantity of mineral reject generation	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					
6	Grade of mineral reject generation and threshold value declared	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					
7	Any analysis or beneficiation study	Not Proposed	NA	NA	No Violation

	proposed & carried out for mineral reject				n
Remark: NIL Remark File: NIL					
8	Manual / Mechanized method adopted for dump working	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					

2.5.1 : OB/Waste Dumps Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Separate dumping of topsoil, OB & mineral rejects, fines, tailings (Rule 36,37)	Dump Type : Waste, Dump ID : Dump:2	Nil	Dump Type : Waste, Dump ID : Dump:2	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
2	Location of Topsoil, OB/Waste, Mineral Reject dumps, Tailings and Fines	Dump Type : Waste, Dump ID : Dump:2, Latitude : 22:15:53.51 , 69:19:34.50, Longitude: 22:15:26.96 , 69:19:34.96	Nil	Dump Type : Waste, Dump ID : Dump:2, Latitude : 22:15:53.51 , 69:19:34.50, Longitude: 22:15:26.96 , 69:19:34.96	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
3	Number of active & Inative dumps	Not Proposed.	NA	NA	No Violation

Remark: NIL Remark File: NIL					
4	Number of dead dumps	Not proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					
5	Number of dumps proposed for stabilised	Not proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					
6	Stabilization Technique (Terracing, plantation, geo-textiles etc.)	Not proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					

2.6.1 : Solid Waste Management - Backfilling (Opencast) Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Status on part or full extraction of mineral from mined out area before starting backfilling	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					

2	Year-wise area under backfilling of mined out area	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					
3	Year-wise topsoil generation, Utilization and Stored proposal (in m3)	Generated :14381.00 Utilized :14381.00 Stored :0.00	Nil	Generation :14381.00 Utilized :14381.00	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
4	Total area fully reclaimed & rehabilitated	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					
5	Locations of proposed reclamation & rehabilitated	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					

2.7.1 : Progressive Mine Closure Plan (PMCP) Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Compliance on	Plantation : Location :Nmax 2461136 Emax	Plantation : Location :Nmax 2461136 Emax	Nil	No

	reclamation and rehabilitation by backfilling/Other means Total area and numbers of plantation proposed.	533678 Nmin 2461054 Emin 533449, Area : 0.2, No. of Plant : 200	533678 Nmin 2461054 Emin 533449, Area : 0.2, No. of Plant : 200		Violation
Remark: NIL Remark File: NIL					
2	Rehabilitation by making water reservoir	Not Proposed	NA	NA	No Violation
Remark: NIL Remark File: NIL					
3	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation	Plantation : Location :Nmax 2461136 Emax 533678 Nmin 2461054 Emin 533449, Area : 0.2, No. of Plant : 200. Fencing-557 meter	Plantation : Location :Nmax 2461136 Emax 533678 Nmin 2461054 Emin 533449, Area : 0.2, No. of Plant : 200. Fencing-557 meter	Nil	No Violation
Remark: NIL Remark File: NIL					
4	Compliance of Environmental monitoring (core zone & buffer zone)	Proposed to Compliance of Environmental monitoring (core zone & buffer zone)	Not carried out.	Deviation reported.	No Violation
Remark: Environmental Clearance and SPCB approvals have not yet been obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					

2.8.1 : Mineral Conservation Details

--	--	--	--	--	--

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	ROM Mineral dispatch or grade-wise sorting within lease area	Grade-wise sorting within lease area	No work carried out.	Deviation reported.	No Violation
Remark: Mining operations not started because Environmental Clearance and SPCB approvals are yet to be obtained from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
2	Different grade of mineral sorted out at mines	Different grade of mineral sorted out at mines	No work carried out.	Deviation reported.	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals are still pending from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
3	Any beneficiation process at mines	Not Proposed.	NA	NA	No Violation
Remark: NIL Remark File: NIL					
5	Utilization of Mineral Rejects or Sub-grade (Blending at ROM stage, Blending after Processing etc.)	Not Proposed.	NA	NA	No Violation
Remark: NIL Remark File: NIL					

2.9.1 : Environment Details

--	--	--	--	--	--

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Separate removal and utilization of topsoil	Proposed for Separate removal and utilization of topsoil. Generation:14381.00 Utilized :14381.00	No work carried out.	Generation:14381.00 Utilized :14381.00	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals are still pending from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
2	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not Proposed.	NA	NA	No Violation
Remark: NIL Remark File: NIL					
3	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not Proposed.	NA	NA	No Violation
Remark: NIL Remark File: NIL					
4	Plantation & Survival rate	Plantation : 200, Survival Rate : 80	Nil	Plantation : 200, Survival Rate : 80	No Violation
Remark: Mining operations and PMCP work have not started because Environmental Clearance and SPCB approvals are still pending from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
5	Water sprinkling on roads to control airborne dust	Proposed for Water sprinkling on roads to control airborne dust.	No work carried out.	Deviation reported.	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals are still pending from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine).					

Remark File: NIL

2.10 : Annual Return Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Submission of Online Monthly and Annual returns in prescribed period or not	Submission of Online Monthly and Annual returns in prescribed period	Last Annual Returns: Yes, on 23/06/2025. Submitted the Online Monthly returns in prescribed period in 2024-25.	Nil	No Violation
Remark: NIL Remark File: NIL					
2	Appointment of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017	Appointment of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017	Geologist appointed. Mining engineer not appointed.	NA	No Violation
Remark: Mining operations have not started because Environmental Clearance and SPCB approvals are still pending from the concerned authority. The lessee has submitted Form-E (Temporary Discontinuance Notice of mine). Remark File: NIL					
3	Whether incomplete or false or wrong returns submitted (Rule 45(7))	Nil	Nil	NA	No Violation
Remark: NIL Remark File: NIL					
4	Status of Approval of FMPCP u/r 24, 25 of MCDR,2017	Not Applicable	Not Applicable	Not Applicable	No Violation
Remark: NIL Remark File: NIL					
5	Notices and Returns for	NA	NA	NA	No

	the lease area submitted or not where fine applicable				Violation
Remark: NIL Remark File: NIL					
6	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	sale value-1 rupees Ex. Mine price: 2809 rupees (Refractory Grade), Production cost: Nil	Sale value- 0.0 rupees Ex. Mine price: 0.0 rupees (Refractory Grade), Production cost: 0.0 rupees	Deviation Reported.	Rule 45(7)
Remark: Mining operations were not undertaken during 2024-25, and the lessee submitted a temporary discontinuance notice. In the Annual Return (AR) for 2024-25, production was shown as Nil; however, a dispatch of 0.7 tonnes was recorded for sampling purposes. This dispatch was reported with a sale value of 1 rupee and an ex-mine price of 2,809 rupees for refractory-grade material. The reporting of sale value and ex-mine price against dispatch made solely for sampling and analysis purposes is incorrect. Remark File: NIL					

2.11 : SDF Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Start Ratings accorded for mine during last 3 years	Year of Submission : 2023-2024 , Rating : 3 Stars, 2024-2025 , Rating: 3 Stars	Year of Submission : 2023-2024 , Rating : 3 Stars, 2024-2025 , Rating: 3 Stars	Nil	No Violation
Remark: NIL Remark File: NIL					

Final Submitted

Part-III : Other Reports

3.1.1 : Upload Other Reports

S.N.	Reports File	Remark File Description
1	1769666483697af7b360520MIDPAS_Report.pdf	MIDPAS_Report
2	1769666483697af7b367090profile.pdf	Profile_sections

Part-IV : Summary Details

4.1 : Summary of Violations

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Annual Return : Scrutiny of Annual return on sale value, Ex. Mine price & production cost	sale value-1 rupees Ex. Mine price: 2809 rupees (Refractory Grade), Production cost: Nil	Sale value- 0.0 rupees Ex. Mine price: 0.0 rupees (Refractory Grade), Production cost: 0.0 rupees	Deviation Reported.	Rule 45(7)
<p>Remark: Mining operations were not undertaken during 2024-25, and the lessee submitted a temporary discontinuance notice. In the Annual Return (AR) for 2024-25, production was shown as Nil; however, a dispatch of 0.7 tonnes was recorded for sampling purposes. This dispatch was reported with a sale value of 1 rupee and an ex-mine price of 2,809 rupees for refractory-grade material. The reporting of sale value and ex-mine price against dispatch made solely for sampling and analysis purposes is incorrect.</p> <p>Remark File: NIL</p>					

Final Submitted

Esigned by: Debajyoti Nayak
Date: 29/01/2026 04:47:50 PM