

INDIAN BUREAU OF MINES

--:-- Inspection Report --:--

Part-I : General Information

1.1.1 Mine Details

Name of the Mine :	38HPR10041	Lease Area (Ha) :	4.194
Forest Area (Ha) :	N/A	Mine Code :	38HPR10041
Registration Number :	IBM/4454/2011	Name of lessee :	AHUJA PLASTICS LTD
Address of lessee :	Care Of Sh Rajinder Singh Thakur ,Village Bedon PO Dadahu, Dadahu	Phone of lessee :	01702-267470
Email of lessee :	Ahujaplastics05@gmail.com	Fax Number :	N/A
Village :	Kolwa (100)	Taluka / Mandal :	Renuka
District :	Sirmaur	Pincode :	173022
State :	Himachal Pradesh	Post Office :	N/A
Nearest Police Station :	N/A	Nearest Railway Station :	N/A
Date of Grant of Mining Lease :	1984-04-30	Date of Mining Lease Execution :	1984-04-18
Date of opening in the mine :	Nilsss		

Nominated Owner Details			
Name of the Nominated Owner :	Smt MAMTA SOOD	Nominated Owner Address:	UTSAV COTTAGE, NEAR KOTSHERA COLLAGE, CHAURAMAIDAN
Nominated Owner Mobile :	9816285000	Nominated Owner Email :	Ahujaplastics05@gmail.com
Nominated Owner Fax Number :	Nil	Date of Nominated Owner Appointment :	2021-11-13
Mining Engineer Details			
Name of the Mining Engineer :	Not Appointed	Qualification of Mining Engineer :	N/A
Address of Mining Engineer :	N/A	Phone of Mining Engineer :	N/A
Email of Mining Engineer :	N/A	Fax Number of Mining Engineer :	N/A
Date of Mining Engineer Appointment :	Nil		
Geologist Details			
Name of the Geologist :	Not Appointed	Qualification of Geologist :	N/A
Address of Geologist :	N/A	Phone of Geologist :	N/A
Email of Geologist :	N/A	Fax Number of Geologist :	N/A
Date of Geologist Appointment :	Nil		
Mine Manager Details			
Name of the Mine Manager :	Not Appointed	Qualification of Mine Manager :	N/A
Address of Mine Manger :	N/A	Phone of Mine Manger :	N/A
Email of Mine Manger :	N/A	Fax Number of Mine Manger :	N/A

Date of Mine Manger Appointment :	Nil		
Mineral(s) granted in lease and proved for mining :	LIMESTONE	Date of Approval of Mining Plan / Modified Mining Plan / ROMP with five-year period :	2026-03-13 (2024 - 2028)
Method of mining :	Open Cast	Category :	OTHER_THAN_MECHANISED
Nature of Use :	Non Captive		

Part-II : Other Information

2.1.1 : Inspection Details

Inspecting Officer :	Matiul Islam
Designation :	Sr ACOM
Name of the Accompanying Official from Mine :	Rajendra Thakur
Designation of the Accompanying Official :	Agent
Type of Inspection :	MPAS
Date of Inspection :	04/02/2026
Review year considered for MCDR Inspection :	2024-2025

Final Submitted

2.2.1 : Exploration Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Number of Core Boreholes	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
2	Number of DTH Boreholes	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
3	Number of exploratory pits / trial pits	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
4	Number of exploratory Trenches	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
5	Lateral exploration status for the lease area	0.00	Nil	0.000	No Violation

	- G1				n
Remark: As per the latest ROMP approved for the mine on 13/03/2026. Remark File: NIL					
6	Lateral exploration status for the lease area-G2	2.77	2.77	0.000	No Violation
Remark: As per the latest ROMP approved for the mine on 13/03/2026. Remark File: NIL					
7	Lateral exploration status for the lease area-G3	1.42	1.42	0.000	No Violation
Remark: As per the latest ROMP approved for the mine on 13/03/2026. Remark File: NIL					
8	Lateral exploration status for the lease area-G4	0.00	Nil	0.000	No Violation
Remark: As per the latest ROMP approved for the mine on 13/03/2026. Remark File: NIL					
9	UNFC category wise reported Resources/Reserves as per MP/MMP ROMP Total Reserves (111, 121 & 122) and Total Mineral Resources (331, 332 & 333 upto 334)	LIMESTONE - Total Reserve 586875.00 , Total Resource 882616.00	LIMESTONE - Total Reserve 586875.00 , Total Resource 882616.00	Nil	No Violation
Remark: As per the latest ROMP approved for the mine on 13/03/2026. Remark File: NIL					

Final Submitted

2.3.1 : Development - Opencast Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Location of development w.r.t. lease area	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
2	Quantity of overburden generation in m3	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
3	Quantity of topsoil generation in m3	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
4	Stripping ratio : ore to OB ratio	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					

2.4.1 Exploitation - Opencast Mine Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Number of pits / Blocks proposed for production	Pit ID : Lapse Period	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
2	Quantity of ROM mineral production proposed (in T)	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
3	Recovery of salable/usable mineral quantity from ROM production in T)	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
4	Quantity of mineral reject/Sub-grade generation	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					

5	Grade of mineral reject/sub-grade generation as per threshold value declared	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
6	Manual/Mechanised method adopted for segregating subgrade/mineral rejects from ROM	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
7	Whether height of benches in Overburden & mineral suitable for method of mining proposed in mining plan	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
8	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					

Final Submitted

2.4.3 : Exploitation - Dump Working Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Number of dumps proposed for production	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
2	Quantity of dump material handling Proposed (in Tonne)	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.. Remark File: NIL</p>					
3	Recovery of salable/usable mineral from dump production (in Tonne)	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
4	Production from dump(s) during the year	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
5	Quantity of mineral reject generation	Nil	Nil	Nil	No Violation

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
6	Grade of mineral reject generation and threshold value declared	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
7	Any analysis or beneficiation study proposed & carried out for mineral reject	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
8	Manual / Mechanized method adopted for dump working	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					

2.5.1 : OB/Waste Dumps Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Separate dumping of topsoil, OB & mineral	Nil	Nil	Nil	No Violation

	rejects, fines, tailings (Rule 36,37)				n
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
2	Location of Topsoil, OB/Waste, Mineral Reject dumps, Tailings and Fines	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
3	Number of active & Inative dumps	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
4	Number of dead dumps	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
5	Number of dumps proposed for stabilished	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
6	Stabilization Technique (Terracing, plantation, geo-textiles etc.)	Nil	Nil	Nil	No Violation

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.ROMP.
Remark File: NIL

2.6.1 : Solid Waste Management - Backfilling (Opencast) Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Status on part or full extraction of mineral from mined out area before starting backfilling	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
2	Year-wise area under backfilling of mined out area	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
3	Year-wise topsoil generation, Utilization and Stored proposal (in m3)	Generated :0.00 Utilized :0.00 Stored :0.00	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
4	Total area fully reclaimed &	Nil	Nil	Nil	No Violation

	rehabilitated				n
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
5	Locations of proposed reclamation & rehabilitated	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					

2.7.1 : Progressive Mine Closure Plan (PMCP) Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Compliance on reclamation and rehabilitation by backfilling/Other means Total area and numbers of plantation proposed.	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
2	Rehabilitation by making water reservoir	Nil	Nil	Nil	No Violation

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.

Remark File: NIL

3	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation	Nil	Nil	Nil	No Violation
---	---	-----	-----	-----	--------------

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.

Remark File: NIL

4	Compliance of Environmental monitoring (core zone & buffer zone)	Nil	Nil	Nil	No Violation
---	--	-----	-----	-----	--------------

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.

Remark File: NIL

2.8.1 : Mineral Conservation Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	ROM Mineral dispatch or grade-wise sorting within lease area	Nil	Nil	Nil	No Violation

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.

Remark File: NIL					
2	Different grade of mineral sorted out at mines	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
3	Any beneficiation process at mines	Nil	Nil	Nil	No Violation
Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL					
5	Utilization of Mineral Rejects or Sub-grade (Blending at ROM stage, Blending after Processing etc.)	Nil	Nil	Nil	No Violation
Remark: NIL Remark File: NIL					

2.9.1 : Environment Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Separate removal and utilization of topsoil	Nil	Nil	Nil	No Violation

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.

Remark File: NIL

2	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Nil	Nil	Nil	No Violation
---	---	-----	-----	-----	--------------

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.

Remark File: NIL

3	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Nil	Nil	Nil	No Violation
---	---	-----	-----	-----	--------------

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.

Remark File: NIL

4	Plantation & Survival rate	Nil	Nil	Nil	No Violation
---	----------------------------	-----	-----	-----	--------------

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.

Remark File: NIL

5	Water sprinkling on roads to control airborne dust	Nil	Nil	Nil	No Violation
---	--	-----	-----	-----	--------------

Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP.

Remark File: NIL

Final Submitted

2.10 : Annual Return Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Submission of Online Monthly and Annual returns in prescribed period or not	Last Annual Returns : No, Last Monthly Returns : Yes - March 2026 - Submitted on : 2026-04-07	Submitted in time	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
2	Appointment of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017	No Appointment Data	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
3	Whether incomplete or false or wrong returns submitted (Rule 45(7))	NA	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
4	Status of Approval of FMPCP u/r 24, 25 of MCDR,2017	Part FMCP approved for an area of 3.886 Ha on 30/12/2025	Part FMCP approved for an area of 3.886 Ha on 30/12/2025	Part FMCP approved for an area of 3.886 Ha on 30/12/2025	No Violation
<p>Remark: Part FMCP approved for an area of 3.886 Ha on 30/12/2025. Final certificate issued by IBM. Remark File: NIL</p>					
5	Notices and Returns for the lease area submitted or not where fine	Nil	Nil	Nil	No Violation

	applicable				
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					
6	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	Nil	Nil	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. No mining plan has been approved since 2013. The mine was inspected for processing of ROMP. Remark File: NIL</p>					

2.11 : SDF Details

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
1	Start Ratings accorded for mine during last 3 years	No Star Rating for Last 3 years	Mine not operational in the last 3 years	Nil	No Violation
<p>Remark: The mine was inoperational since the year 2010 for want of Forest Clearance and other statutory clearances. The mine has not participated in Star Ratings. Remark File: NIL</p>					

Final Submitted

Part-III : Other Reports

3.1.1 : Upload Other Reports

S.N.	Reports File	Remark File Description
1	NIL	Nil

Part-IV : Summary Details

4.1 : Summary of Violations

S.N	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule
-----	---------------------	-----------------------------	--------	-----------	----------------------

Final Submitted

Esigned by: Matiul Islam
Date: 18/05/2026 06:08:22 PM